

Roll No.

--	--	--	--	--	--	--	--	--	--

No. of Printed Pages—3

ME-404

B. TECH.

FOURTH SEMESTER EXAMINATION, 2003–2004

MEASUREMENT AND METROLOGY

Time : 2 Hours

Total Marks : 50

Note : (1) Attempt **ALL** questions.

(2) Marks are shown against each question.

1. Attempt any **FOUR** of the following :— (3·5×4=14)

(a) Enumerate desirable static performance characteristics of measuring instruments. Explain the terms, **DEAD ZONE** and **HYSTERESIS**.

(b) The temperature of a furnace is increased at the rate of 240 °C per hour. The measuring instrument used should not show an error of more than 8 °C. What maximum time constant is permissible, if the instrument has a first order type response ?

(c) Explain the principle of operation of a **L.V.D.T.**

(d) Explain how a compound gear-train can be used to achieve amplification of a mechanical signal.

(e) The resistance **R** of a circuit is found by measuring the current and the power fed into the circuit. Find the limiting error in measurement of **R**, if the limiting errors in the measurement of power and current are $\pm 1.5\%$ and $\pm 1.0\%$ respectively.

(f) Describe the construction and operation of a D'ARSONVAL galvanometer.

2. Attempt any FOUR of the following :— (3×4=12)

- (a) Describe the principle and operation of a stroboscopic tachometer.
- (b) Sketch the basic functional form of a seismic instrument. How is the same instrument used for measurement of displacement as well as acceleration ?
- (c) What is a ring balance and how is it used for measurement of pressure ?
- (d) A strain gauge having an electrical resistance of 120 ohms and a gauge factor of 2.1 is used to test a steel specimen subjected to an axial tensile load. Calculate the induced strain if the increase in gauge resistance is shown to be 0.134 ohms.
- (e) Describe, with the help of a sketch, a hydraulic load cell for force measurement.
- (f) What does IPTS stand for ? Describe the functioning of a disappearing filament type optical pyrometer.

3. Attempt any TWO of the following :— (6×2=12)

- (a) Why are comparators used in metrology ? Describe, with the help of a sketch, the essential features of a SIGMA comparator.
- (b) What are the devices commonly used for precision measurement of angles ? Explain how a precision spirit level can be used for this purpose.
- (c) Write short notes on :
 - (i) Slip gauges

(iii) Unilateral and bilateral system of tolerances

(iv) The meaning of $50 H_7$ in the context of limit and fits.

4. Attempt any TWO of the following :— (6×2=12)

(a) What are the important parameters which should be checked while inspecting a precision screw thread ? Describe, briefly, the three-wire method for ascertaining the effective diameter of a screw thread.

(b) Explain the meaning of the following terms with reference to surface finish and its measurement :—

(i) Roughness

(ii) Waviness

(iii) LAY

(iv) Sampling Length

(v) Ra Value

(vi) Ten point height of irregularities (R_z)

(c) What do you understand by the term, "flatness" ? What methods are used for checking flatness ?